


URGENT SAFETY NOTICE

Point Source Productions Ltd



Lighting Hire, Sales & Service
Rear of 37 Station Road
Belmont
Surrey
SM2 6DF

Tel: 020 8661 7200
Fax: 0870 284 9007
Email: service@pslx.co.uk



Dear Sir/Madam, this letter is of importance to anyone who uses stage lighting control equipment and relates to potentially dangerous components used in dimming equipment manufactured before 1990.

In 1990 the manufacturer of these components issued a memo to the effect that all these particular capacitors produced between 1979 and 1990 could fail in use with potentially hazardous results.

These can be; toxic fumes, fire and electrical hazard. The company recommended that all potentially faulty components be replaced with new ones of an improved specification.

It has come to our attention, through equipment we have been requested to service, that many people are still unaware of this situation and, as can be seen from the photographs on the left, these components are now failing with serious consequences.

In order to prevent future failure we strongly recommend the immediate replacement of these components.

The faulty components are not specific to just one manufacturer of dimmers and may not even have been replaced in equipment that has had regular servicing.

Point Source can offer a free on-site inspection of your dimmers to check the suppression capacitor type and recommend any action required.

Our engineer will then prepare a quotation for the replacement of the capacitors if necessary. Prices are usually no more than £75.00 plus vat per dimmer pack. During service at our workshops the dimmer will be cleaned internally, tested and any other faults reported before commencing further repair (as instructed)

If you would like Point Source to give your dimming equipment a free, no obligation safety inspection please contact us by phone, fax or email.

Yours sincerely, Ben Marshall, Technical Director,
Point Source Productions Ltd.

